BOUNDARY SURVEY FOR JACK RINDLISBACH 870 IRONWOOD DRIVE MESQUITE, NV 89027 FOUND 5/8" REBAR PLAT 7, MT. TABBY SPRINGS DUCHESNE COUNTY, UTAH SURVEYOR'S CERTIFICATE I, Clinton S. Peatross, Duchesne, Utah, do hereby certify that I am a Registered Land Surveyor, and that I hold License No. 155666, as prescribed by the laws of the state of Utah, and that I have made a survey of the following described tract of land: PROPERTY DESCRIPTION Lots 54, 55, and 56, Plat 7, Mt. Tabby Springs, Duchesne County, Utah. FOUND 5/8" REBAR I further certify that the visible improvments effecting the boundaries of the above described tract of land, are as shown on this plat. FOUND 5/8" REBAR **NARRATIVE** 52 PURPOSE OF SURVEY: To find the original lot corners and/or re-set those missing with BASIS OF BEARING: The basis of bearing was taken from data on the subdivision plat on file in the Duchesne County Recorder's Office.

SURVEY FINDINGS: I found and used original corners as shown on the plat for the control to 53 *57* N 88°35'15"E set the missing corners. NOTE: This survey was performed at the request of Jack Rindlisbach and does not guarantee ownership or show liens or rights of way recorded or unrecorded. LOT 54 LOT 56 WARRANTY DEED: BOOK A 204 PAGE 444-445 LOT 55 FOUND 5/8" REBAR SCALE 1" = 50'

■= 1/2" x 24" REBAR SET DURING THIS SURVEY

□= 5/8" REBAR FOUND DURING THIS SURVEY COUNTY SURVEYOR'S FILE # 957 PREPARED BY PEATROSS LAND SURVEYS P.O. BOX 271 DUCHESNE, UT 84021 (435) 738-5753 JOB # 806